


STORAGE UNIT
COMFORT 1.1 MD
ТУМБА ДЛЯ ХРАНЕНИЯ



SYMBOLS




INDICATING MARK

ОБОЗНАЧЕНИЕ



ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА



EVEN SURFACE












РОВНАЯ ПОВЕРХНОСТЬ






OPERATION


ЭКСПЛУАТАЦИЯ


010007	1x	010011	2x	010012	2x
010013	2x	010023	1x	010024	1x
010025	1x	010026	1x	010027	1x
010028	3x				

1x  020004	1x  020005	1x  020006	1x  020011	1x  020012	2x 020018 
5x 020013 CR 		5x 020013 CL 		4x 020021 	
5x 020015 DL 		5x 020015 DR 			

	030001 21x  3 * 16	030002 44x  3,5 * 16	030003 10x  6,2 * 50	030006 4x  2,9 * 13	030008 2x  φ 4
030009 2x  M4 * 20	030011 10x  φ 15	030012 4x  φ 18	4x 030013  L 35	030014 4x  φ 15 h 12	
4x 030015  φ 8 * 30	4x 030016  φ 8 * 30	030017 4x  φ 15 h 12	030022 4x  M 10	030023 4x  φ 10	

1x 050004 	2x 050005 	S4 1x 
---	---	--





10
 4x 030001
 2x 020015 DR

030016 **7**
 4x

9
 4x 030017


2x 010012

2x 010013

10
 2x 020015 DL
 4x 030001

2x 010011

8
 4x 030015




12
 020015 DL 2x
 4x 030001

11
 2x 050005
 8x 030002

2x 010028

12
 4x 030001
 2x 020015 DR



14
 1x 020015 DL
 2x 030001

13
 1x 050004
 4x 030002

1x 010028

14
 2x 030001
 1x 020015 DR

