


STORAGE UNIT
COMFORT 2.1.2 MD
ТУМБА ДЛЯ ХРАНЕНИЯ




SYMBOLS




INDICATING MARK
ОБОЗНАЧЕНИЕ



ASSEMBLY & ADJUSTMENT
СБОРКА РЕГУЛИРОВКА





EVEN SURFACE
РОВНАЯ ПОВЕРХНОСТЬ





OPERATION
ЭКСПЛУАТАЦИЯ


010007	1 x	010011	3x	010012	3x
010013	4x	010014	1 x	010015	1 x
010023	1 x	010024	1 x	010025	1 x
010026	1 x	010027	1 x	010028	2x
010034	1 x	010038	1 x	010039	1 x
010040	1 x	010043	1 x		


020004 1x  020005 1x	2x  020006	1x  020011	1x  020012	020018  4x
6x 020013 CR 	6x 020013 CL 	2x 020016 	020021 	
6x 020015 DL 	6x 020015 DR 	4x 020020 	4x 	

030001 26x  3 * 16	030002 48x  3,5 * 16	030003 18x  6,2 * 50	030033 2x  4,2 * 13	030006 4x  2,9 * 13	030008 4x  φ 4	
030009 4x  M4 * 20	030011 18x  φ 15	030012 6x  φ 18	6x 030013  L 35	030014 6x  φ 15 h 12	030028 8x  3,9 * 16	
030015 14x  φ 8 * 30	8x 030016  φ 8 * 30	030017 8x  φ 15 h 10	4x 030061  M 8	030060 4x  φ 8	030031 4x  φ 8 s2,5	030038 4x  2,5 * 20

1x 050002 	1x 050004 	1x 050005 
1x 050003 		
S4 1x 		







17

030001
2x




1x 020015 DR




18

030002
4x

1x 050004



1x 010028



17




1x 020015 DL

030001
2x



22

6x
030001




3x 020015 DR



030016 19
6x


21

6x
030017



3x 010013

3x 010012



22



3x 020015 DL

6x
030001










3x 010011

20

6x 030015





1x 010040

1x 010038



1x 010039

1x 010013

1x 010043

