



STORAGE UNIT
COMFORT 2.1 MD
ТУМБА ДЛЯ ХРАНЕНИЯ




SYMBOLS




INDICATING MARK
ОБОЗНАЧЕНИЕ



ASSEMBLY & ADJUSTMENT
СБОРКА РЕГУЛИРОВКА





EVEN SURFACE
РОВНАЯ ПОВЕРХНОСТЬ





OPERATION
ЭКСПЛУАТАЦИЯ

010007	1 x	010011	5x	010012	5x
010013	5x	010014	1 x	010015	1 x
010023	1 x	010024	1 x	010025	1 x
010026	1 x	010027	1 x	010028	5x





020004 1x  020005 1x 020006	1x  020011	1x  020012	2x  020016	020018  4x
10x 020013 CR 		10x 020013 CL 		020021 4x 
10x 020015 DL 		10x 020015 DR 		


030001 42x  3 * 16	030002 76x  3,5 * 16	030003 14x  6,2 * 50	030006 4x  2,9 * 13	030009 4x  M4 * 20	030008 4x  φ 4	030011 14x  φ 15
030012 6x  φ 18	6x 030013  L 35	6x 030014  φ 15 h12	16x 030015  φ 8 * 30	10x 030016  φ 8 * 30		
030017 10x  φ 15 h10	030060 4x  φ 8	4x 030061  M 8	030031 4x  φ 8 s2,5	030028 8x  3,9 * 16	030038 4x  2,5 * 20	



2x 050004 	3x 050005 	S4  1x
---	---	---



010023









5x 010012

5x 010013





5x 010011

14

10x 030015



3x 010028



2x 010028

