


SEWING MACHINE TABLE
COMFORT 7 (C 7+)
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK



ОБОЗНАЧЕНИЕ




EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ

010001 1x		010002 1x		010003 1x		010004 1x	
010006 1x		010007 1x		010008 1x		010010 1x	
010011 1x		010012 1x		010013 1x		010015 1x	
010023 1x		010024 1x		010025 1x		010026 1x	
010027 1x		010028 1x		010030 1x		010031 1x	
010032 1x							

020001  4x		020002  4x		020003  2x		020004 2x  020005 2x 			
020006  2 x		020008  2 x		020010 L 660  2 x		020011  1x		020012  1x	
3 x 020013 CR 				3 x 020013 CL 					
3 x 020015 DR 				3 x 020015 DL 					
2x 020016 									


030001  3 * 16 60x	030002  3,5 * 16 36x	030003  6,2 * 50 18x	030006  2,9 * 13 6x	030033  4,2 * 13 34x	030038  2,5 * 20 4x
030008  φ4 4x	030009  M4 * 20 4x	030011  φ15 18x	030012  φ18 12x	030013  L = 35 12x	030014  φ15 h12 13x
030015  φ8 * 30 14x	030016  φ8 * 30 2x	030017  φ15 h10 2x	030018  φ8 * 15 1x		

1 x 050001 	1 x 050002 
1x 050004 	2x 050005 



1x S4 
--









COMFORT 7+












010018 1x 010019 1x	020001 1x 	5x 020019 	030033  4,2 * 13 23x
--	---	---	--




*
Входит в комплект стола.
Included into table set.








S 4



* Входит в комплект стола.
Included into table set.








A



B






COMFORT 7 +

36

12 x 030033


3 x 020019

35

8 x 030033




2 x 020019



34

020001




1x 030033

3 x

