


SEWING MACHINE TABLE
COMFORT 8
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS




ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ








INDICATING MARK

ОБОЗНАЧЕНИЕ



EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ

010001 1x		010002 1x		010003 1x		010004 1x	
010006 1x		010007 1x		010011 2x		010012 2x	
010013 2x		010023 1x		010024 1x		010025 1x	
010026 1x		010027 1x		010029 1x		010030 1x	
010031 1x		010033 1x					
020001  2x		020002  2x		020003  1x		020004 1x  020005 1x 	
020006  1x		020008  1x		020009  L300 1x		020010  L660 1x	
				020011  1x		020012  1x	
2x 020013 CR 				2x 020013 CL 			
2x 020015 DR 				2x 020015 DL 			
020021  4x		2 x 020022 		030038			
030001  3 * 16 46x	030002  3,5 * 16 12x	030003  6,2 * 50 22x	030038  2,5 * 20 4x	030033  4,2 * 13 15x	030006  2,9 * 13 4x		
030008  φ4 2x	030009  M4 * 20 2x	030011  φ15 22x	030012  φ18 12x	030013  L = 35 12x	030014  φ15 h12 12x		
030015  φ8 * 30 16x	030016  φ8 * 30 4x	030017  φ15 h10 4x	030061  M 8 4x	030060  φ8 4x	030024  5 * 50 2x		
1x  S3		1x  S4		 030031 4x φ8 s2,5			



S 4



010002

010001

3 **2x** 
030006
1x 
020004

5

6x
030013 

6x
030015 

4

2 **4x**  **030011**
4x  **030003**

010003

010004

6

6x 
030014

6x 
030012

1 **020001**

2x



030033
6x 

1 **020002**

2x



030033
6x 

010006

4

*Входит в комплект стола.
Included into table set.*

12

030002

4 x

020008

1 x

13

020005

1 x

030001

2 x


9

020022

2 x

030001

4 x



14

030006

2 x

020012

1 x

8

020011

1 x

030038

4 x

7

020003

1 x

030033

3 x

11

030008 030009

2 x

020006

1 x

10

020010

1 x

030001

22 x



18 6x 030011
6x 030003

010030

15
030002
4x
2x 020013 CR

010027

16
030003
4x
030011
4x

010024

17
030003
6x
030011
6x

010033



010031






010026





010025

19
4x 030061
4x 030031
4x 030060
4x 020021


15
020013 CL
2x
030002
4x







4



030024

020022

5

