

SEWING MACHINE TABLE

COMFORT EASY plus

СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS




ATTENTION

ВНИМАНИЕ



ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ




STORAGE

ХРАНЕНИЕ




INDICATING MARK

ОБОЗНАЧЕНИЕ




EQUALITY

РАВЕНСТВО






EVEN SURFACE


РОВНАЯ ПОВЕРХНОСТЬ




STEP No

НОМЕР ОПЕРАЦИИ

010001 1x 010002 1x 010004 1x 010006 1x 010007 1x 010011 2x 010012 2x 010013 2x 010015 1x 010026 1x 010028 1x 010030 1x 010033 1x 010034 1x				
020003 2x 	020006 2x 	020011 2x 	020012 2x 	020018 4x 
020019 3x 	020020 4x 	020056 	020084 2x 	
3x 020013 CR 		3x 020013 CL 		
3x 020015 DR 		3x 020015 DL 		

030001 3 * 16 20x 	030002 3,5 * 16 28x 	030003 6,2 * 50 14x 	030038 2,5 * 20 8x 	030033 4,2 * 13 22x 	030006 2,9 * 13 4x 
030008 φ4 4x 	030009 M4 * 20 4x 	030011 φ15 14x 	030012 φ18 6x 	030013 L = 35 6x 	030014 φ15 h12 6x 
030015 φ8 * 30 8x 	030016 φ8 * 30 4x 	030017 φ15 h10 4x 	030028 3,9*16 8x 		

1 x 050001 	1 x 050002 	1x 050004 
1x S4 	1 x 050003 	





010007

5


030008 030009

4x  4x 

2x  020006

6

020011

2x 

8x  030038

7

020003

2x 

6x  030033

010015

010001

030015

10

4x 

11

030013

6x 

12

6x  030014

6x  030012

010007

010015

9

020012 030006

2x  4x 









8

8x  030028

12x  030002

4x 020018





010002

19



2x 020084

20




12x




030033



3x 020019



1x 010034



23

4x 020020



21

2x 030033

1x 050001



22



1x 050003



1x 050002

2x

030033



