



SEWING MACHINE TABLE

COMFORT EASY

СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS




ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ




STORAGE

ХРАНЕНИЕ




INDICATING MARK

ОБОЗНАЧЕНИЕ




EQUALITY

РАВЕНСТВО



EVEN SURFACE


РОВНАЯ ПОВЕРХНОСТЬ



STEP No



НОМЕР ОПЕРАЦИИ

010009	1x	010013	1x	010018	1x	010022	1x
010023	1x	010024	1x	010025	1x	010027	1x
010029	1x	010030	1x				

020024	020049	020034	020086
4x 	4x 	4x 	2x 

030001	030003	030005	030011	030012	030013	030014
						
3,0 * 16	6,2 * 50	4,2 * 16	φ 15	φ 18	L 35	φ 15 h 12
16x	13x	10x	13x	15x	15x	15x
030015						
						
φ 8 * 30						
11x						

1x 050006 	1x S 4 
--	---





14 030013
10x 

010023

030015 **15**
9x 

16 **10x** 
030014
10x 
030012

010029

6x 030005 
2x 020086
18 


4x 
030001
8x 

4x 020024
17 

=

4x 020056
17 

010018


030005
4x  **19**

20 **1x** 050006