


SEWING CHEST SINGLE

ШВЕЙНЫЙ СУНДУК SINGLE



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK

ОБОЗНАЧЕНИЕ





EVEN SURFACE


РОВНАЯ ПОВЕРХНОСТЬ

010001	1x	010002	1x	010003	1x	010004	1x	010006	1x
010022	1x	010026	1x	010032	1x	010033	1x	010044	1x


1x 020013 CR 		1x 020013 CL 	
1x 020015 DR 		1x 020015 DL 	
1x 020007 	4x 020035 	1x 020037 	

030001  3 * 16 4x	030002  3,5 * 16 13x	030003  6,2 * 50 4x	030009  M4 * 20 1x	030011  φ15 4x	030012  φ18 22x
030013  L = 35 22x		030014  φ15 h12 22x	030015  φ8 * 30 26x	030028  3,9 * 16 16x	

1x 050004 	1x 050006 	1x S4 
---	--	---



S 4



4

***** *Входит в комплект стола.
Included into table set.*

030013

4

12x



5



12x 030014



12x 030012

2



030002

2x



1x

020013 CR



12x 030015

3



010006

010004

010026



020013 CL

1x

2



030002

2x



7



030003

4x



030011

4x

6







030028

16x

4x 020035







010032



010044

