


STORAGE UNIT
COMFORT 1.1 MD
ТУМБА ДЛЯ ХРАНЕНИЯ




SYMBOLS




INDICATING MARK
ОБОЗНАЧЕНИЕ



ASSEMBLY & ADJUSTMENT
СБОРКА РЕГУЛИРОВКА





EVEN SURFACE
РОВНАЯ ПОВЕРХНОСТЬ





OPERATION
ЭКСПЛУАТАЦИЯ



010007 1x			010011 2x			010012 2x		
010013 2x			010023 1x			010024 1x		
010025 1x			010026 1x			010027 1x		
010028 3x								

020004 1x  020005 1x	1x  020006	1x  020011	1x  020012	 020018 2x
5x 020013 CR 		5x 020013 CL 		020021 4x 
5x 020015 DL 		5x 020015 DR 		

030001 22x  3 * 16	030002 40x  3,5 * 16	030003 10x  6,2 * 50	030006 4x  2,9 * 13	030008 2x  φ 4	030028 4x  3,9 * 16
030009 2x  M4 * 20	030011 10x  φ 15	030012 4x  φ 18	4x 030013  L 35	030014 4x  φ 15 h 12	030038  2,5 * 20 4x
4x 030015  φ 8 * 30	4x 030016  φ 8 * 30	030017 4x  φ 15 h 10	030061 4x  M 8	030060 4x  φ 8	030031 4x  φ 8 s2,5

1x 050004 	2x 050005 	S4  1x
---	---	--





2x 010012

2x 010013

2x 010011

8

4x 030015

