


STORAGE UNIT
COMFORT 2.1 M
ТУМБА ДЛЯ ХРАНЕНИЯ




SYMBOLS




INDICATING MARK
ОБОЗНАЧЕНИЕ



ASSEMBLY & ADJUSTMENT
СБОРКА РЕГУЛИРОВКА






EVEN SURFACE
РОВНАЯ ПОВЕРХНОСТЬ




OPERATION
ЭКСПЛУАТАЦИЯ


010011	2 x	010012	2 x	010013	4x
010014	1 x	010015	1 x	010023	1 x
010024	1 x	010025	1 x	010026	1 x
010027	1 x	010028	2x	010034	1 x
010035	1 x	010036	1 x	010037	1 x
010038	1 x	010039	1 x	010040	1 x
010041	1 x	010042	1 x	010043	1 x


 	5x  020006	1x  020011	1x  020012	020018  2x
6x 020013 CR 	6x 020013 CL 	4x 020016 	020021 	
6x 020015 DL 	6x 020015 DR 	4x 020020 		









030001 26x  3 * 16	030002 48x  3,5 * 16	030003 24x  6,2 * 50	030033 2x  4,2 * 13	030006 4x  2,9 * 13	030008 10x  φ 4	030038 4x  2,5 * 20
030009 10x  M4 * 20	030011 24x  φ 15	030012 6x  φ 18	6x 030013  L 35	030014 6x  φ 15 h12	030028 4x  3,9 * 16	
14x 030015  φ 8 * 30	8x 030016  φ 8 * 30	030017 8x  φ 15 h10	4x 030061  M 8	030060 4x  φ 8	030027 2x  M4 * 35	030031 4x  φ 8 s2,5

1x 050004 	1x 050005 	1x 050002 
		1x 050003 

S4 1x 
--
















010028

010041











2x 010013

2x 010011

2x 010012






1x 010036




1x 010037

1x 010013

1x 010042

1x 010035





1x 010040

1x 010038



1x 010039

1x 010013

1x 010043

