

SEWING MACHINE TABLE
COMFORT 9
СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK



ОБОЗНАЧЕНИЕ




EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ


010001 1x	010002 2x	010004 1x	010006 1x
010007 1x	010011 2x	010012 2x	010013 2x
010015 1x	010020 2x	010026 1x	010028 1x
010030 1x	010033 1x	010034 1x	

020001  2x	020003  2x	020004 2x  020005 2x 	020006  2 x
---	---	--	--

020011  2x	020012  2x	020018  4x	10x 020019  	020020  4x	020034 4x 
--	--	--	--	--	--

3 x  020013 CR	3 x  020013 CL
---	--

3 x  020015 DR	3 x  020015 DL
---	--

030001  3 * 16 16x	030002  3,5 * 16 28x	030003  6,2 * 50 14x	030038  2,5 * 20 8x	030033  4,2 * 13 56x	030006  2,9 * 13 8x	
030008  φ4 4x	030009  M4 * 20 4x	030011  φ15 14x	030012  φ18 6x	030013  L = 35 6x	030014  φ15 h12 6x	030028  3,9*16 8x
030015  φ8 * 30 8x	030016  φ8 * 30 4x	030017  φ15 h10 4x	030061  4x M 8	030060  φ8 4x	030031  φ8 s2,5 4x	

1 x  050001	1 x  050002	1x  050004
1x  S 4	1 x  050003	



S 4 *

S 5



S 10
S 12



2
8x 030011
8x 03003

1
030002
6x
020013 CR
3x

010030

010033

010006


010004

010026

3
4x 030061
4x 030031
4x 030060
4x 020034

1
020013 CL
3x
030002
6x

4
6x 030011
6x 030003

6 020011
2x 
8x  030038

5 030008 030009
4x  **4x** 
2x  020006

7 020003
2x 
6x  030033

010007

010015

8 **4x**  030006
2x  020004

010001


9 030015
4x 


10 030013
6x 


010015

11 **6x**  030014
6x  030012

010007

14 020005
2x 
4x 030001 


12 **8x**  030028
12x  030002
4x 020018 

13 020012 030006
2x  **4x** 

17

24x 030033





6x 020019

16

16x 030033





4x 020019

15

020001



2x

030033

6x 

2x 010002

2x 010020


21

1x 010034

20 4x 020020



19



1 x 050003



1 x 050002

2 x 030033



18

2 x 030033


1 x 050001





030033



4mm








2x 010012


2x 010013



2x 010011







1x 010028






1



2



3

